


Replacement Sheet
Application No. 10/801,307
Art Unit: 3752

FIG 2 (Prior Art)




BEST AVAILABLE COPY

Replacement Sheet
Application No. 10/801,307
Art Unit: 3752

FIG 3 (Prior Art)


20



BEST AVAILABLE COPY

Replacement Sheet
Application No. 10/801,307
Art Unit: 3752

FIG 4 (Prior Art)




SECTION B-B

BEST AVAILABLE COPY

Replacement Sheet
Application No. 10/801,307
Art Unit: 3752

FIG 5 (Prior Art)




BEST AVAILABLE COPY

Replacement Sheet
Application No. 10/801,307
Art Unit: 3752

FIG 6 (Prior Art)


90



BEST AVAILABLE COPY

Replacement Sheet
Application No. 10/801,307
Art Unit: 3752

FIG 7 (Prior Art)




BEST AVAILABLE COPY

Replacement Sheet
Application No. 10/801,307
Art Unit: 3752

FIG 8 (Prior Art)


40



BEST AVAILABLE COPY

Replacement Sheet
Application No. 10/801,307
Art Unit: 3752

FIG 9



BEST AVAILABLE COPY

New Sheet
Application No. 10/801,307
Art Unit: 3752

FIG 17A





FIG 17B



BEST AVAILABLE COPY